



U.S. Department
of Transportation
**Federal Aviation
Administration**

FEDERAL AVIATION ADMINISTRATION - PARTS MANUFACTURER APPROVAL

**Aviation Technical Services
3121 109th St. SW
Everett, WA 98204**

**PMA No. PQ5315NM
Supplement No: 54
Date: November 25, 2020**

Article Name	Article Number	Approved Replacement for Article Number	Approval Basis and Approved Design Data	Make/TCH Eligibility	Model/Series Eligibility
Inner Chord, Galley Entry Door	654A0004- 134ATSMRO	654A0004-134	Test and Computations per 14 CFR § 21.303 <u>DWG. No.:</u> 780251-MDL-001 <u>Rev.:</u> B <u>Date:</u> 10/9/2020 or later FAA-approved revision	Boeing	737-600 Series 737-700 Series 737-800 Series 737-900 Series 737-900ER Series 737-8 737-9
Inner Chord, Fwd Entry Door	654A0004- 1073ATSMRO	654A0004-1073	Test and Computations per 14 CFR § 21.303 <u>DWG. No.:</u> 780251-MDL-001 <u>Rev.:</u> B <u>Date:</u> 10/9/2020 or later FAA-approved revision	Boeing	737-600 Series 737-700 Series 737-800 Series 737-900 Series 737-900ER Series 737-8 737-9

-----END OF LISTING-----

GENERAL NOTES:

Provide minor design changes in a manner as determined by the ACO. Process major design changes to drawings and specifications in the same manner as that for an original FAA-PMA.

The FAA accepted the ICA approach for the above articles with their designs. These ICA may refer to those of the respective articles from the holders of type certificates. Otherwise, provide supplemental ICA for differences in the replacement articles. Make referral statements or supplemental ICA readily available per 14 CFR § 21.50.

/Signature on file/

Ian Won
Aviation Safety
Manager, Seattle ACO Branch
Compliance & Airworthiness Division
Aircraft Certification Service

Michael D. Saludares
Aviation Safety Inspector, Seattle Mido Section
System Oversight Division
Aircraft Certification Service