

## Federal Aviation Administration

## FEDERAL AVIATION ADMINISTRATION - PARTS MANUFACTURER APPROVAL

Aviation Technical Services PMA No. PQ5315NM 3121 109<sup>th</sup> St. SW Supplement No. 133

Everett, WA 98204 Date 10/1/2025

Article Name	Article Number	Approved Replacement for Article Number	I I	Make/TCH Eligibility	Model/Series Eligibility
Intercostal – Floor, AFT Lavatory	147A5660Y21 ATSPMA	147A5660Y21	Test and Computations per 14 CFR 21.303 <u>DWG No:</u> 781980-MDL-001 <u>Rev:</u> A <u>Date:</u> 9/4/2025 or later  FAA-approved revisions	The Boeing Company	737-700 Series 737-800 Series 737-8
Intercostal – Floor, AFT Lavatory	147A5660U22 ATSPMA	147A5660U22	Test and Computations per 14 CFR 21.303 DWG No: 781980-MDL-001 Rev: A Date: 9/4/2025 or later FAA-approved revisions	The Boeing Company	737-700 Series 737-800 Series 737-8

-----End of Listing-----

## **GENERAL NOTES:**

Provide minor design changes in a manner as determined by the cognizant FAA certification branch. Process major design changes to drawings and specifications in the same manner as that for an original FAA PMA.

The FAA accepted the instructions for continued airworthiness (ICA) approach for the above articles with their designs. These ICA may refer to those of the respective articles from the holders of type certificates. Otherwise, provide supplemental ICA for differences in the replacement articles. Make referral statements or supplemental ICA readily available per 14 CFR 21.50.

\_\_\_\_\_Signature On File\_\_\_\_\_\_
for Gregory S. DiLibero, Manager
West Certification Branch
Compliance & Airworthiness Division
Aircraft Certification Service

for Donald Henchar, Acting Manager Seattle Certificate Management Section West Certificate Management Branch Systems Oversight Division Aircraft Certification Service