



U.S. Department  
of Transportation  
Federal Aviation  
Administration

## **FEDERAL AVIATION ADMINISTRATION - PARTS MANUFACTURER APPROVAL**

Aviation Technical Services  
3121 109<sup>th</sup> St. SW  
Everett, WA 98204

**PMA NO.: PQ5315NM**  
**SUPPLEMENT NO. : 40**  
**DATE: September 24, 2019**

Article Name	Article Number	Approved Replacement for Article Number	Approval Basis & Approved Design Data	Make/TCH Eligibility	Model/Series Eligibility
Doubler Assy	149A7244Y2ATSM RO	149A7244Y2 149A7244-2	Test and Computations per 14 CFR § 21.303 <u>DWG. No.:</u> 780242-MDL- 001 <u>Rev.:</u> A <u>Date:</u> 08/16/2019 or later FAA-approved revision	Boeing	737-600 Series 737-700 Series 737-700C Series 737-800 Series 737-900 Series
Doubler Assy	149A7244Y4ATSM RO	149A7244Y4	Test and Computations per 14 CFR § 21.303 <u>DWG. No.:</u> 780242-MDL- 001 <u>Rev.:</u> A <u>Date:</u> 08/16/2019 or later FAA-approved revision	Boeing	737-600 Series 737-700 Series 737-700C Series 737-800 Series 737-900 Series

---

### **END OF LISTING**

---

#### GENERAL NOTES:

Provide minor design changes in a manner as determined by the ACO. Process major design changes to drawings and specifications in the same manner as that for an original FAA-PMA.

The FAA accepted the ICA approach for the above articles with their designs. These ICA may refer to those of the respective articles from the holders of type certificates. Otherwise, provide supplemental ICA for differences in the replacement articles. Make referral statements or supplemental ICA readily available per 14 CFR § 21.50.

/Signature on file/

Michael D. Saludares  
Aviation Safety  
Aviation Safety Inspector, Seattle  
MIDO Section

---

Paul Bernado  
Aviation Safety  
Acting Manager, Seattle ACO Branch