



U.S. Department
of Transportation
Federal Aviation
Administration

FEDERAL AVIATION ADMINISTRATION - PARTS MANUFACTURER APPROVAL

Aviation Technical Services
3121 109th St. SW
Everett, WA 98204

PMA NO.: PQ5315NM
SUPPLEMENT NO. : 47
DATE: January 29, 2020

| Article Name | Article Number | Approved Replacement for Article Number | Approval Basis & Approved Design Data | Make/TCH Eligibility | Model/Series Eligibility |
|----------------------------|------------------|--|--|-------------------------|---|
| Seat Track - Section 44 | 144A5350-1ATSMRO | 144A5350-1 | Test and Computations per 14 CFR § 21.303 <u>DWG. No.:</u> 780414-MDL-001 <u>Rev.:</u> - <u>Date:</u> 12/18/2019 or later FAA-approved revision | Boeing | 737-600 Series 737-700 Series 737-700C Series 737-800 Series 737-900 Series 737-900ER Series 737-8 737-9 |
| Seat Track - Section 44 | 144A5350-3ATSMRO | 144A5350-3 | Test and Computations per 14 CFR § 21.303 <u>DWG. No.:</u> 780414-MDL-001 <u>Rev.:</u> - <u>Date:</u> 12/18/2019 or later FAA-approved revision | Boeing | 737-600 Series 737-700 Series |

-----END OF LISTING-----

GENERAL NOTES:

Provide minor design changes in a manner as determined by the ACO. Process major design changes to drawings and specifications in the same manner as that for an original FAA-PMA.

The FAA accepted the ICA approach for the above articles with their designs. These ICA may refer to those of the respective articles from the holders of type certificates. Otherwise, provide supplemental ICA for differences in the replacement articles. Make referral statements or supplemental ICA readily available per 14 CFR § 21.50.

(SIGNATURE ON FILE)

Ross Landes
Aviation Safety
Manager, Seattle ACO Branch

Michael D. Saludares
Aviation Safety
Aviation Safety Inspector, Seattle
MIDO Section